

Cement Code Changing

You can't get cement, NSN 8040-01-084-3861, to fix the drooping door seals on your OH-58's—at least not yet. Right now, the cement's coded for depot use only in the Acquisition Advice Code (AAC) column on the AMDF. The code's being changed, tho, so units can get it. Until the change makes the AMDF, you can use cement, NSN 8040-00-165-8614.