



Careful, Kiowa mechs, when you drill out rivets in your bird's airframe to replace a windshield.

Shavings can fall into the J600 plug that holds the impedance matching network and circuit card at the rear of the instrument panel.




APR 88

If the shavings get into the circuit card's contacts, they short out your commo gear.

That adds up to a lot of grief in repair time and cost.

So next time, before you drill out rivets on a windshield, remove the circuit card from the plug and put a strip of duct tape over the plug. This will protect the circuit card.



39