

Noisy Pump A-OK!

The T63-A-720 engine fuel pump used on the OH-58C is a bit noisy during starting and coastdown due to the design of the lube groove on the bearing. No sweat! Table 4-1 in TM 55-2840-241-23 lists the actual causes for replacing a faulty fuel pump.