


A Reel Solution

Aircraft shoulder harness inertia reel, NSN 1680-00-775-4182, can now be repaired by support. When you remove a faulty reel, forget the "nonrecoverable" code in the AH-1, UH-1, CH-54, and OH-58 parts pubs. TSARCOM Supply Letter 33-82 says to ship the reel to:

Sharpe Army Depot
ATTN: RIC AQ5, W62G2T
Lathrop, CA 95330



FORGET THE
"NONRECOVERABLE"
CODE!



Inertia
Reel