

## Get Just the Knob

Dear Editor,

It costs \$13 to replace the hinge assembly (Item 13 of Figure 41 in TM 55-1520-228-23P) on the side plate of our seat armor.

Yet, that's what we have to do because vibration shakes the knob off the assembly and it gets lost.

We've found two knobs that work as replacements. NSN 5355-00-827-8682 brings a smaller knob that costs just 29 cents. NSN 5355-01-037-0835 brings a larger knob that costs \$1.14

Once we have the replacement knob, we lock it in place with sealant, NSN 8030-00-067-6744.

Use sealant, NSN 8030-00-067-6744, to secure replacement knob



CW2 John W. Pearce  
Salina, KS

(Editor's note—Thanks. Saving \$12 may not seem like a lot, but multiplied by all the OH-58s it's quite a chunk of change.)