



Spray no water or cleaning solvents on the helpless core of your OH-58A's oil cooler or directly on the pylon isolation mount.

PROTECT YOUR OIL COOLER WHILE CLEANING YOUR BIRD



Shield the cooler with a locally-made cover, which you remove after cleaning your bird.

Water or solvent can run through the core of the oil cooler assembly . . . down into the fabric air ducts . . . and get trapped in the lowest part of a duct. The trapped liquid causes the duct to rot.

Liquids can work under the edges of the top boot of the pylon isolation mount and get inside the mount.

The elastomeric dampener of the mount can separate from the mount frame, leading to air-frame vibration and lateral spike knocking.

... AND THAT'S BAD NEWS ALL AROUND...

SO BE SURE TO COVER THE COOLER WHILE CLEANING THE BIRD!

