

UNCLASSIFIED

MSG DTG 081745Z JUL 14

FROM COMMANDER, AMCOM, REDSTONE ARSENAL, AL //AMSAM-SFA//

SUBJECT - AVIATION SAFETY ACTION MESSAGE (ASAM), MAINTENANCE MANDATORY, ALL OH-58D SERIES AIRCRAFT, REVISED OVERHAUL AND RETIREMENT SCHEDULE, H-58-14-ASAM-04

NOTE

This message is issued per AR 750-6 to Commanders of Army Commands (ACOM), Army National Guard (ARNG), Army Service Component Commands (ASCC), and Direct Reporting Units (DRU). Commanders must retransmit this message to all subordinate organizations. Notify the AMCOM SOF compliance officer at "usarmy.redstone.amcom.mbx.safety-sof-team@mail.mil" when complete.

NOTE

Per AR 750-6, commanders/directors in the grade of major general or civilian equivalent may authorize temporary exception from message requirements. These exceptions may only occur during combat operations, matters of life or death in civil disasters, or other emergencies when aircraft operation is required.

NOTE

Commanders unable to comply with the requirements of this message within the time frame specified will change the affected aircraft status symbol to a Grounding //X//.

NOTE

Commanders, facility managers, and contractors at all levels will not issue aircraft until they are in compliance with this message. Aircraft transferred to the U.S. Government via DD Form 250 after the message DTG are in compliance with message requirements.

NOTE

A listing of all messages and any required reports, supplements, or addendums can be downloaded at: "<https://asmprd.redstone.army.mil>".

1. SUMMARY -

1.1. Background - As a result of an updated Flight Loads Survey and Fatigue Life Substantiation Report, the Retirement Change (RC) Life Limits for numerous dynamic components have

changed or been added. Additionally, DA Form 2408-34 "OH-58D Pylon Support Components Record" dated 28 Feb 14 has been rescinded and replaced with DA Form 2408-34 Revised "OH-58D Pylon Support Components Record" dated 18 Jun 14.

1.2. Message Purpose -

1.2.1. Revise RC Life Limits of select components.

1.2.2. Initiate DA Form 2410 tracking of additional flight control components.

1.2.3. Provide "DA Form 2408-34 Revised" dated 18 Jun 14.

1.2.4. Adjust "DA Form 2408-34 Revised" data to reflect new computation formulas.

1.2.5. Require Technical Manual (TM) changes.

2. END ITEMS AFFECTED - All OH-58D series aircraft.

3. ASSEMBLIES/COMPONENTS/PARTS AFFECTED - As per Part 1 of Addendum 1 to H-58-14-ASAM-04.

4. INITIAL AIRCRAFT TAMMS-A (THE ARMY MAINTENANCE MANAGEMENT SYSTEM - AVIATION) ENTRY -

NOTE

When complying with the requirements of this message, complete forms and records entries per DA PAM 738-751. ULLS-A units will use appropriate "E" forms.

Upon receipt of this message, make the following entry on the DA Form 2408-13-1. Enter a Horizontal Dash //-// status symbol with the following statement: "Comply with requirements of H-58-14-ASAM-04 by 06 AUG 14."

5. COMPLIANCE REPORTING REQUIREMENTS -

NOTE

Report compliance with this message via the AMCOM Message Tracking System (AMTRACKS) at ["https://amtracks.redstone.army.mil"](https://amtracks.redstone.army.mil). Unit personnel designated to submit reports must establish a profile in AMTRACKS.

5.1. Aircraft Initial Compliance Report - All reporting requirements will be accomplished as part of the "Final Compliance Report".

5.2. Aircraft Final Compliance Report - Submit the report via AMTRACKS by 09 AUG 14 per AR 750-6. This report will include the Aircraft SN, MDS, Date of initial TAMMS-A Entry, and check the box "Entered on DA Form 2408-15".

- 5.3. Retail Stock Task/Inspection Compliance Report (Installation level and below) - N/A.
- 5.4. Wholesale Stock Task/Inspection Compliance Report (including Depot Stock, Depot Maintenance, and Overhaul/Repair Facilities) - N/A.

6. SPECIAL PROVISIONS TO MESSAGE REQUIREMENTS (AIRCRAFT) -

NOTE

For message purposes, aircraft away from home station are defined as those not having access to a maintenance facility capable of meeting all message requirements.

Aircraft in Transit (surface/air shipment/ferry status/ aircraft away from home station) - Unit commanders unable to comply with the requirement specified in paragraph 4 may defer making the initial aircraft TAMMS-A entry until arrival at final destination. Adjust the date in the TAMMS-A entry to be 30 days after arrival at destination.

7. TECHNICAL PROCEDURES/INSTRUCTIONS - Unless otherwise stated, all message requirements shall be completed by the suspense date listed in paragraph 4.

NOTE

This message includes Two (2) required addendums. If the addendums are not received with this message, they may be viewed/downloaded at "<https://asmprd.redstone.army.mil>".

NOTE

Requests for exceptions (waivers) to this message will be submitted per GEN-14-AMAM-01, Message Exception (Waiver) Process, and AR 750-6. For help, contact the AMCOM Safety POC in paragraph 13.5.1.

7.1. Refer to the Part 1 of Addendum 1 to H-58-14-ASAM-04. Add or update the component RC Life Limit times on DA Form 2408-16 and, if applicable, DA Form 2408-34 Revised to reflect the revised tracking requirements listed for each applicable component as follows.

NOTE

The Maintenance Consolidated Database System (MCDS) Legitimate Code File (LCF) may be viewed/downloaded at "<https://tamms-a.redstone.army.mil>". This is a secure website which requires an Army Knowledge Online (AKO) user ID and password and approved MCDS access.

7.1.1. **UNIT LEVEL LOGISTIC SYSTEM - AVIATION (ENHANCED) (ULLS-A(E)) USERS** - Access MCDS and use the Script File provided under "APPS", "ULLS LCF LOAD", "H-58-14-ASAM-04 OH-58D REVISED OVERHAUL AND RETIREMENT SCHEDULE" to update the parts LCF.

7.1.2. **Non-ULLS-A (E) USERS** - Make manual records changes to update the parts LCF as provided in Part 1 to Addendum 1.

7.1.3. Refer to Addendum 2 to H-58-14-ASAM-04. Units shall implement the use of DA Form 2408-34 Revised.

7.1.3.1. Instructions for use of DA Form 2408-34 Revised are included in Part 2 of Addendum 1.

7.1.3.2. To meet DA Form 2408-34 Revised requirements, legacy data will be recalculated and updated by the 2410 Hotline System Manager Subject Matter Experts (SMEs) at the DA Form 2410 Hotline.

7.1.3.3. Contact the 2410 Hotline System Manager SME POC in paragraph 13.4 for any suspect data discrepancies.

7.2. Initiate DA form 2410 tracking of components listed in Part 1 of Addendum 1 which were not previously tracked.

7.2.1. Inspect the installed component to determine the Serial Number (SN), Part Number (PN), and National Stock Number (NSN).

7.2.2. If the SN of the part cannot be determined, contact the 2410 Hotline System Manager SME POCs in paragraph 13.4 for further instructions.

7.2.3. Prepare DA Form 2410 GAIN Copy and DA Form 2410 INSTALL Copy. If the installation date and Time Since New (TSN) cannot be determined, compute the TSN of the applicable part as fifty percent of the new RC time or current aircraft hours, whichever is lower.

7.3. Clear the initial entry from paragraph 4 and note compliance on DA Form 2408-15.

8. PROCEDURES/INSTRUCTIONS FOR ASSEMBLIES/COMPONENTS/PARTS IN WORK OR IN STOCK (AT ALL LEVELS INCLUDING WAR RESERVES) - N/A.

9. SPECIAL TOOLS AND FIXTURES REQUIRED - N/A.

10. SUPPLY/PARTS (REQUISITION/DISPOSITION) - N/A.

11. MAINTENANCE APPLICATION - Field at Aviation Maintenance Company.

12. PUBLICATION REQUIREMENTS -

12.1. References -

12.1.1. AR 750-6.

12.1.2. DA Pam 738-751.

12.1.3. DA Pam 25-40.

12.1.4. TB 1-1500-341-01.

- 12.1.5. TM 1-1520-248-23&P.
- 12.2. Publication Changes - The following publications shall be changed to reflect this message. A copy of this message and the addendum will be used as authority to implement the change until the official TM change is received.
- 12.2.1. DA PAM 738-751. Chapter 4 Historical Forms and Records, paragraph 4-18. CHANGE paragraph 4-18 DA Form 2408-34 instructions to the DA Form 2408-34 Revised instructions per Part 2 of Addendum 1.
- 12.2.2. TB 1-1500-341-01. UPDATE the TM to reflect the new components as listed in Part 1 of Addendum 1.
- 12.2.3. TM 1-1520-248-23&P, Overhaul and Retirement Schedule, WP 0394-00. Refer to Part 1 of Addendum 1. CHANGE Overhaul and Retirement schedule for applicable components to reflect this message.

13. POINTS OF CONTACT -

- 13.1. Technical POCs -
- 13.1.1. Primary - Mr. Joe Wathen (Avion), DSN 788-2499 or 256-842-2499. Fax: DSN 897-5688 or 256-313-5688. Email: "joseph.e.wathen.ctr@mail.mil".
- 13.1.2. Alternate - Mr. Tim Tucker, DSN 897-5685 or 256-313-5685. Fax: DSN 788-6758 or 256-842-6758. Email: "timothy.w.tucker24.civ@mail.mil".
- 13.2. Project/Product Manager's (PM) Office POCs -
- 13.2.1. Primary - Mr. Charles Wright, DSN 645-7077 or 256-955-7077. Fax: DSN 645-7125 or 256-955-7125. Email: "charles.d.wright.civ@mail.mil".
- 13.2.2. Alternate - Mr. Jack McRoberts, DSN 645-8265 or 256-955-8265. Fax: 897-1541 or 256-313-1541. Email: "ellis.j.mcroberts.civ@mail.mil".
- 13.3. Wholesale Materiel POC (DLA) - Ms. Felicia Barwell, DSN 695-5208 or 804-279-5208. Fax: DSN 897-1541 or 256-313-1541. Email: "felicia.barwell@dla.mil".
- 13.4. 2410 Hotline System Manager SME POCs -
- 13.4.1. Primary - Mr. Lenox (Sammy) Fields, DSN 645-9389 or 256-955-9389. Email: "lenox.fields.civ@mail.mil".
- 13.4.2. Alternate - Mr. Marvin A. Winfrey, DSN 746-5970 or 256-876-5970. Email: "marvin.a.winfrey.civ@mail.mil".
- 13.5. Forms and Records POCs -
- 13.5.1. TAMMS-A (Primary) - Mr. Dean Geiselhart, DSN 788-2971 or 256-842-2971. Email: "dean.d.geiselhart.civ@mail.mil".
- 13.5.2. MCDS/LCF (Primary) - Mr. Jeff Sutherland, DSN 788-0860 or 256-842-0860. Email: "jeffrey.a.sutherland.civ@mail.mil".
- 13.5.3. TAMMS-A and MCDS/LCF (Alternate) - Mr. Lloyd Willits, DSN 746-3598 or 256-876-3598. Email: "lloyd.e.willits.civ@mail.mil".

- 13.6. AMCOM Safety POCs -
 - 13.6.1. Safety (Primary) - Mr. William (Bill) Kennedy, DSN 788-8630 or 256-842-8630. Email: "william.l.kennedy4.civ@mail.mil".
 - 13.6.2. Safety (Alternate) - Mr. Don Swallom, DSN 788-8641 or 256-842-8641. Email: "donald.w.swallom.civ@mail.mil".
 - 13.6.3. AMTRACKS (Primary) - Mr. Vic Mosley, DSN 788-8620 or 256-842-8620. Email: "victor.e.mosley.civ@mail.mil".
 - 13.6.4. AMTRACKS (Alternate) - Ms. Teri Phipps, DSN 897-2097 or 256-313-2097. Email: "teri.l.phipps.civ@mail.mil".
- 13.7. Foreign Military Sales POCs -
 - 13.7.1. Primary - Ms Tina Pizits, DSN 746-9019 or 256-876-9019. Email: "tina.m.pizitz.civ@mail.mil".
 - 13.7.2. Alternate - Ms. Janett H. Carter, DSN 645-2653 or 256-955-2653 Email: "janett.h.carter.civ@mail.mil".
 - 13.7.3. Alternate - Mr. Robert Dubose, DSN 788-1068 or 256-842-1068. Email: "robert.w.dubose.civ@mail.mil".