


TIP TOP ELEMENTS

When any of the elements in the engine inlet particle separator are damaged the organizational maintenance pub allows you to tape over up to 25, before replacing the filter.



YOU CAN
TAPE OVER
UP TO 25
ELEMENTS

If any of those elements were accidentally pushed in, tho, never figure them as damaged elements.

Latch on to a pair of long-nose pliers and gently re-set the element by pulling it back out . . . no sweat.



PULL
'EM OUT

Right-on . . . pulling maintenance by-the-book. You don't have the time to do the job over.