


KIOWA SIMPLE BATTERY CHECK



CHECK
BATTERY BY
SWITCHING
BATTERY
OFF...
CHECK
AMPERAGE
DROP.


To find out if the nickel cadmium battery is up to par without sending it to the battery shop, here's a check the pilot can make.

With the bird cranked up, move the battery switch to OFF.

If you get a drop of less than 5 amps, the battery is fully charged.



THANKS
FOR THE TIP
ON THE
BATTERY
CHECK,
CONNIE.



OK... BUT
REMEMBER
THIS IS NO SUB-
STITUTE FOR
THE PM CHECKS
AND SERVICES
CALLED FOR IN
CHAP. 4, TM 11-6140-
203-15-2
(1 DEC 69).