

A VISUAL CHECK

Dear Windy,

Sequence 4.6 of TM 55-1520-228-20PMP (May 72) says to inspect the engine mounts for security, cracks and damage. There is no inspection poop in TM 55-1520-228-20 (Oct 72), however.


TM 55-1520-228-34 (Nov 72), para 5-13, says to dye penetrant inspect the tubes and welds for cracks. Is this what we should do at the organizational maintenance level, Windy?

SP6 R.S.

Dear Specialist R.S.,

Nosir-e-e-e! The dye penetrant deal is for your support outfit, after they remove the mounts from the bird.

ONLY A
VISUAL CHECK
ON MOUNTS



JUST
EYEBALL
THE ENGINE
MOUNTS,
SPEC!



IF YOU SUSPECT
THEY'RE BAD, CALL ON
YOUR SUPPORT FOR
MORE THOROUGH
INSPECTION!