



## Bolt Switch OK

View B, Fig 11-4, TM 55-1520-228-23, shows that you install the middle bolt on the cyclic bellcrank with the bolt head inboard. But that's hard to do with the OH-58's hydraulic pump in the way. So, on the left side only, make it easy on yourself and install bolt, NSN 5306-00-927-4302, with the head outboard.