

## Saves Downtime

Special inspections for your OH-58A/C may now be pulled within plus-or-minus 10 percent of the flight-hour figures listed in Para 1-49 of TM 55-1520-228-23.

READ ALL ABOUT  
THIS IMPORTANT  
CHANGE IN  
TSARCOM  
Msg. 061930Z  
Apr 82!

60

