



Kiowa Parts Kit



Got a bum particle separator on your OH-58? Fix it with repair kit, NSN 2945-01-018-2486. The kit includes instructions for repair of the separator and will show up in a change to TM 55-1520-228-23P. Eyeball Para 4-46 of TM 55-1520-228-23-1 for some good info on the kit.